## 3.6 GAS PRESSURE SENSOR (P1)

Inside the P1 device there's the P1 sensor, measuring rail absolute pressure.

This device is preamplified, so jamming the signal is very difficult. It's easy-to-install, thanks to its pre-cabled connection.

Pict. 8
P1 Sensor